

Release Notes

Date: 25 September 2026

Title: Software update for #REC2
Product ID: SREC-3000
Reason for Change: ☐ Hardware ☒ Software ☐ Other _____
Description of Changes Performance 1. Faster and more accurate PWM channel reading – single glitches are filtered out. 2. SBUS reading reworked – corrected channel mapping, receiver failsafe is treated as signal loss. 3. Full radio stick travel (988–2012 μs) is now accepted on all channels. 4. Fixed glitch that would cause a freeze if camera packet is lost. Improved camera detection. 5. Hotshoe feedback and timelapse (with Feedback disabled or OUTPUT) now work reliably. Software tools 1. Seagull-REC2-Config_1.5.exe – no longer freezes if #REC2 does not respond; a clear error is shown instead. 2. Decimal values always use "." regardless of PC region settings; a typed "," is converted automatically. 3. Settings can be written only after they have been read, preventing accidental writes of empty values.